

Vehicle Inspection Form

Sales Vehicle:

Registration No.: Make, Model, Colour:

Date & Time Tested:

NK07ZDS Aston Martin Vantage (Silver) 06-03-2025 13:42

SKU No.: VIN No.:

Mileage:

V2539 SCFBA03B97GC05085

99999

Page 1 of 2

Exterior Check:		
Doors – opening, closing & locking		
Boot lid & fuel cap - operation		
Sunroof/roof mechanism - operation & condition	0	
Windows - operation & condition	0	
Lights - operation & condition		
Horn - operation		
Washers & wipers - operation & condition	0	
Spare wheel & tools - security & condition	0	
Locking wheel nut	0	
Parking sensor/camera - operation & condition	0	

Interior Check:	
Seats - security and condition	0
Seatbelts - operation and condition	Ø
All interior lights - operation	0
Rear view mirrors - operation and condition	0
Trim, fittings and glovebox - security and condition	Ø
Instrument panel illumination	Ø
Radio and ICE	0
Sat nav system	0

Engine Compartment:	
All fluid levels	\bigcirc
Coolant / antifreeze strength	0
Auxiliary drive belt-tension and condition	0
Wiring pipes and hoses-security and condition	0
All mountings - security and condition	0
Check for visible leaks	Ø
Check for abnormal noises	0

Wheels & Tyres Check:	
Tyre Wear NSF Inner:6mm Centre:6mm Outer:6mm OSF Inner:6mm Centre:6mm Outer:6mm NSR Inner:6mm Centre:6mm Outer:6mm OSR Inner:6mm Centre:6mm Outer:6mm	
Road wheels-condition	0
Wheel Nut Torque: 105	
Tyre Pressure (PSI) - FRONT: 28	
Tyre Pressure (PSI) - REAR: 28	
Wheel bearings - condition	\bigcirc
Brake Discs & PADS - Condition & Wear - FRONT: OK	(
Brake Discs & PADS - Condition & Wear - REAR: OK	

Page 2 of 2

Underside Check:		
Front suspension - security and condition		
Rear suspension - security and condition		
Steering, rack and linkage - security and condition		
Brake pipes, hoses & calipers	\bigcirc	
Fuel tank and pipes - security and condition		
Exhaust system - security and condition		
Check for any fluid leaks		
General underbody condition		
Side steps	\bigcirc	
Diffs and four-wheel-drive system		
Suspension and steering bushes & gators - integrity	0	

Road Test:	
Instruments and warning lights operation	0
Clutch/operation	0
Gear change / kickdown	0
Engine performance	0
Abnormal noises	0
Engine / gearbox / suspension / steering / chassis	0
Brake performance [including hand brake and ABS operation]	0

Final Checks:		
Re-check for fluid leaks	0	
Tune in radio and set clock		
Check diagnostic systems	\bigcirc	

Technician signature:		
AHQ Admin		